

Sevenmile Creek Stream Corridor Photos



Pre-Construction - Bank Erosion



Pre-Construction - Bank Erosion



Pre-Construction – Slump near Fence and Driveway



Pre-Construction – Slump near Fence and Driveway

Sevenmile Creek Stream Corridor Photos



Construction – Early Stage Clearing



Construction – Bank Taper



Construction – Log Vane Installation



Construction – Top-of-Bank Matting


Sevenmile Creek Stream Corridor Photos



Native Plants Arrive



Native Plants Arrive



Walking Workshop



Project Completion